

**FOLLOW-UP ASSESSMENT OF A
MULTI-RESIDENTIAL COMPLEX
IN WHITEHORSE, YUKON**

PREPARED FOR

The CANMET Energy Technology Centre (CETC)
Energy Technology Branch, Energy Sector
Natural Resources Canada
Ottawa, Ontario, Canada, K1A 0E4
DSS File No.23441-96-2134/001-SQ
March, 1997

PREPARED BY:

William J. Mayhew, P.Eng.
Howell-Mayhew Engineering, Inc.
15006 - 103 Avenue
Edmonton, Alberta
Tel: (403)484-0476; Fax: (403)484-3956

SCIENTIFIC AUTHORITY:

Frank Szadkowski
The CANMET Energy Technology Centre (CETC)
Energy Technology Branch, Energy Sector
Natural Resources Canada
580 Booth Street, 13th Floor
Ottawa, Ontario, Canada K1A 0E4

CITATION

Willian J. Mayhew, P. Eng., Howell-Mayhew Engineering, Inc., *Follow-up Assessment of a Multi-Residential Complex in Whitehorse, Yukon.* The CANMET Energy Technology Centre, (CETC), Energy Technology Branch, Energy Sector, Natural Resources Canada, Ottawa, Ontario, 1996 (20 pages).

Copies of this report may be obtained through the following:

The CANMET Energy Technology Centre (CETC)
Energy Technology Branch, Energy Sector
Department of Natural Resources Canada
580 Booth Street, 13th Floor
Ottawa, Ontario,
K1A 0E4

or

Intellectual Property and Technical Information Management
Library and Documentation Service Division, CANMET
Department of Natural Resources Canada
562 Booth Street
Ottawa, Ontario
K1A 0G1

DISCLAIMER

This report is distributed for informational purposes only and does not necessarily reflect the views of the Government of Canada nor constitute an endorsement of any commercial product or person. Neither Canada nor its ministers, officers, employees or agents make any warranty in respect to this report or assumes any liability arising out of this report.

TABLE OF CONTENTS

EXECUTIVE SUMMARY RESUME	i ii
1. BACKGROUND	1
2. INTRODUCTION	1
3. INTERVIEW WITH THE BUILDING OWNER AND THE BUILDING OPERATOR	1
4. REVIEW OF RECOMMENDATIONS FROM MARCH 1993 FINAL REPORT	3
4.1 Building Envelope Recommendations	3
4.2 Heat Recovery and Ventilation	4
4.3 Space and Domestic Hot Water Heating Systems	5
4.4 Cooling System	5
4.5 Electrical System	5
5. INSPECTION AND ASSESSMENT OF THE HVAC SYSTEM	6
5.1 Domestic Hot Water Heating System	6
5.1.1 Dedicated Boiler for Summer Mode Heating	6
5.1.2 Back-up DHW Heating System	7
5.2 Boiler and Space Heating System	7
5.2.1 Boiler Controller	7
5.2.2 Three-way Valve	8
5.2.3 Boiler Cycling	8
5.2.4 Barometric Damper Settings and Chimney Oversizing	9
5.3 Ventilation System	9
5.3.1 Mechanical Room Inspection	9
5.3.2 Suite Inspection	10
5.4 Cooling System	11
6. SUITE INSPECTION	11
7. OPERATION AND MAINTENANCE REVIEW	12
7.1 Fuel and Electricity Consumption	12
7.2 Repair and Maintenance Costs	12
8. CONCLUSIONS AND RECOMMENDATIONS	13
8.1 Recommendations	14
Appendix A	A1

Executive Summary

The Level B monitoring of Closeleigh Manor in Whitehorse, Yukon was completed in July 1992 and the final report, *Monitoring and Investigation of a Multi-Suite Residential Complex in Whitehorse, Yukon from 1988 to 1992*, was submitted to Natural Resources Canada (NRCan) in March 1993. As a result of the recommendations of that report, a number of mechanical system changes were carried out. The most significant changes were the renovations made to the domestic hot water heating and ventilation systems.

NRCan was interested in conducting a follow-up investigation to determine the building's current operation and maintenance status and evaluate any changes which had occurred since initial monitoring was completed in 1992. The investigation included interviews with the Yukon Housing Corporation (YHC), the building owner, and Whitehorse Housing Authority (WHA), responsible for operating and maintaining the building; inspections of the mechanical systems and the individual suites; and computerized monitoring of specific mechanical system components.

The investigation showed that Closeleigh Manor was being well maintained and that YHC and WHA had responded well to addressing the recommendations put forth in the March 1993 report. The interviews and inspections identified problems highlighted in the March 1993 report which had not yet been addressed, and uncovered new problems which required further investigation. The discovery of a major problem with the original space heating system piping design once again emphasized the need for thorough building commissioning.

The follow-up investigation raised a number of issues and questions which must still be addressed and answered. They are presented as recommendations and include renovation work that is to be completed, investigative work that should be carried out after the renovations are completed, and suggestions for ensuring a continued high level of building maintenance and operation.

Résumé

Le contrôle de niveau B du Closeleigh Manor, à Whitehorse (Yukon), s'est terminé en juillet 1992 et le rapport final, intitulé *Monitoring and Investigation of a Multi-Suite Residential Complex in Whitehorse, Yukon from 1988 to 1992*, a été présenté à Ressources naturelles Canada (RNCan) en mars 1993. Conformément aux recommandations du rapport, on a apporté un certain nombre de changements au système mécanique, dont les plus importants ont été les travaux de réfection des systèmes de chauffage à eau chaude et de ventilation.

NRCAN a décidé d'effectuer une enquête de suivi afin d'évaluer où en sont, aujourd'hui, le fonctionnement et l'entretien du bâtiment et de déterminer quels changements ont été apportés depuis le premier contrôle, en 1992. L'enquête a été menée sur plusieurs fronts : entrevues avec la Yukon Housing Corporation (YHC), avec le propriétaire du bâtiment et avec le Service de logement de Whitehorse (SLW) (responsable du fonctionnement et de l'entretien des locaux); inspections des systèmes mécaniques et des suites; et contrôle informatisé de certains éléments du système mécanique.

L'enquête a permis de constater que le Closeleigh Manor était bien entretenu et que la YHC ainsi que le SLW avaient tenu compte des recommandations du rapport publié en mars 1993. Les entrevues et les inspections ont mis en lumière certains problèmes mentionnés dans le rapport de 1993 qui n'avaient pas encore été réglés, ainsi que de nouvelles lacunes nécessitant un examen plus approfondi. La découverte d'un problème grave concernant la conception originale de la canalisation du système de chauffage des locaux a une fois de plus démontré la nécessité d'effectuer des inspections rigoureuses avant l'occupation des bâtiments.

Il reste encore à régler un certain nombre de questions et de points soulevés par l'enquête de suivi. Ils sont présentés sous forme de recommandations et incluent les travaux de rénovation à terminer, le travail d'enquête qui devra suivre les rénovations et des propositions en vue d'assurer un fonctionnement et un entretien de qualité.