

LOCK OUT!

The bottom line
before working on any machine:

LOCK – TAG – TEST!



STEPS...

- 1 Turn off the machine at the operator's control panel.
- 2 Install the lock. Remember: one worker – one key – one lock!
- 3 Attach the tag that identifies you and when you locked out.
- 4 De-energize the machine. Careful, all types of energy must be released.
- 5 Test to ensure the machine won't start.



Revised January 2006

