

IMPORTANT NOTICE TO OUR VALUED CUSTOMERS.


Consistent with our commitment to product safety and reliability, LG Canada continues to offer a retrofit program, launched in June 2005, for selected refrigerator models, based on a discovery that a faulty component can potentially malfunction and may pose a **RISK OF FIRE**.

This notice is part of our aggressive program, in conjunction with our retail partners, to contact consumers who purchased affected models. If you have an affected 3- or 2-door model (see model numbers below), please unplug your refrigerator immediately and arrange for a service visit by calling 1-888-542-2623 to schedule an in-house retrofit at the earliest opportunity. LG is providing free in-home repairs to the following LG refrigerators that were manufactured between May 2004 and October 2004, and sold in Canada between June 2004 and April 2005.


Only the following LG-branded models with serial numbers beginning with **405, 406, 407, 408, 409** and **410** are affected:

WHERE TO LOOK FOR MODEL & SERIAL NUMBERS

3-DOOR MODEL #
LRFC 21760ST/SW
LRFC25750SB/ST/SW/TT/WW



2-DOOR MODEL #
GR-729RN
LRTX 18311 WW
LRTN 18320 WW
LRTX 18321 BK/TT/WW



Customers with an affected refrigerator are requested to contact LG immediately at 1-888-542-2623, or by email at retrofit@lge.com

