Water Facts



The Manitoba Water Services Board

Box 22080

Brandon, MB

R7A 6Y9

(204) 726-6076

SEALING ABANDONED WELLS

March, 2000

Why?

<u>Safety</u>: Abandoned large diameter wells are dangerous. People, animals or equipment can fall into them causing injury or death.

Environmental: Wells are direct orifices to aquifers. Spilled fuels or chemicals near or in abandoned wells can cause groundwater contamination. Polluted surface waters can pollute wells.

How?

- <u>Step 1</u>: Get as much information on the well as you can. Sources are the Groundwater Section of the Water Resources Branch and well drillers. They will need the land location (section, township and range) and, if possible, the names of the original owner and the driller. If wells flow or are contaminated, qualified contractors should do the abandonment.
- <u>Step 2</u>: Disconnect any electrical service to the well. Remove pumps, hoses or anything else in the well. If the clear depth of the well is close to the original reported depth, then sealing can proceed (see Step 3). If there are obstructions, these should be removed. If they can't be removed, call a drilling contractor, Water Resources or The Manitoba Water Services Board for further advice.
- **Step 3:** Chlorinate, then start backfilling the well with a fine to medium sand (preferably silty sand). For small diameter wells (less than 15 inches), place a shovelful or two of bentonite chips or pellets every 20 to 30 feet of hole filled. For large diameter wells, place a layer (approximately 6 inches) of bentonite just below the water table. Backfill the wells to approximately 3 or 4 feet below ground level. Leave the wells sit for a period of time (1 or 2 weeks) to allow the fill to settle. The top 3 or 4 feet of the well can then be dug up and clay and soil placed over the cut-off well.

Step 4: Fill out an "Abandoned Well Report" and send to Water Resources (see reverse).

Contacts

Groundwater Section, Water Resources Box 18, 200 Saulteaux Crescent Winnipeg MB R3J 3W3

Phone: 945-7400

The Manitoba Water Services Board

Box 22080, 2022 Currie Blvd. Brandon MB R7A 6Y9 Phone: 204-726-6076

Fax: 204-726-6290

E-mail: farmwater@gov.mb.ca

Drilling Contractors – See Yellow Pages or contact the above agencies.

Information prepared by: The Manitoba Water Services Board, Box 22080, 2022 Currie Blvd., Brandon, MB R7A 6Y9 For further information, please contact your Regional Farm Water Source Technologist at one of the following locations:

Wes Friesen Dauphin, MB (204)622-2116 Rob Sykes Brandon, MB (204)726-6078 Mursel Kluke Beausejour, MB (204)268-6059

	L	لـــــــا					-	Abar	idon	ed \	Nell Report	Mani Natu	ral Resources
	VELL	QTR SEC TWP RGE E W										LOCATION SK	ETCH OF WELL
	WELL DWNER ADDRESS PHONE									HONE			
WE	LL IDENT	NTIFICATION (NO., NAME)											
I —		PRODUCTION		TES	T WFI	ιП							
W.	ATER USE	DOMESTIC [] [IVEST		M							
DAT	ATE WELL CLOSED DAY L MONTH YEAR												
ORIGINAL DATE WELL COMPLETED DAY MONTH YEAR													
	DEPTH BELOW GROUND IN FEET FROM TO			OPEN HOLE	SAND	GRAVEL	BENTONITE	CEMENT	CLAY	OTHER	MATE	ERIAL	OTHER
=	•		-	ļ				-	ļ				
WELL ABANDONMENT			 	 									
ΙΘ̈́													
18A							<u></u>						
					ļ								
₹						 	 						
			1										
			ļ										
-			ļ	-									
1 -			-	├					 				
-		ASING OR P				F	EET A	BOVE [B	ELOW	GROUND LEVEL	ABANDONED	WELL SKETCH
REMARKS: CONDITION OF WELL, ETC.													
	LICENCE NO. L								sw	/L	LL INFORMATION ABOVE GRD BELOW GRD		
CTOR										SING S	.		
CONTRACTOR	ADDRESS										CUT OFF AT		
	OPERATOR										BELOW GRD.		· ·
	Signature of Contractor										<u> </u>		