

8 REFERENCES

- 1) Allan, J. A., and R. L. Rutherford. 1934. Alberta Geological Survey. Geology of Central Alberta. [AGS Report 30]
- 2) Borneuf, D. M. 1983. Alberta Geological Survey. Springs of Alberta. [QE 186 P7 No. 82-03]
- 3) Buchanan, Bob (editor). Alberta Agriculture, Food and Rural Development. Engineering Services Branch. Alberta Environment, Licensing and Permitting Standards Branch, Canada. Prairie Farm Rehabilitation Administration. 1996. Water Wells ... that Last for Generations.
- 4) CAESA. November 1997. Alberta Farmstead Water Quality Survey. Prepared for CAESA Water Quality Monitoring Committee.
- 5) CAESA-Soil Inventory Project Working Group. 1998. AGRASID: Agricultural Region of Alberta Soil Inventory Databsae (Version 1.0). Edited by J. A. Brierley, B. D. Walker, P. E. Smith and W. L. Nikiforuk. Alberta Agriculture Food & Rural Development, publications.
- 6) Carlson, V. A. 1971a. Alberta Geological Survey. Bedrock Topography of the Rocky Mountain House Map Area, Alberta. NTS 83B. [AGS MAP 058]
- 7) Carlson, V. A. 1971b. Alberta Geological Survey. Bedrock Topography of the Wabamun Lake Map Area, Alberta. NTS 83G. [AGS MAP 057]
- 8) Demchuk, Thomas D., and L. V. Hills. 1991. A Re-examination of the Paskapoo Formation in the Central Alberta Plains: the Designation of Three New Members *in* Canadian Petroleum Geology. Volume 39, No. 3 (September 1991), P. 270-282.
- 9) Edwards, D., D. Scafe, R. Eccles, S. Miller, T. Berezniuk, and D. Boisvert. 1996. Alberta Geological Survey. Mapping and Resource Exploration of the Tertiary and Preglacial Sand and Gravel Formations of Alberta. [QE 186 Op94-06]
- 10) Gabert, G. M. 1975. Alberta Geological Survey. Hydrogeology of Red Deer and Vicinity, Alberta. Red Deer Area. [QE 186 R415 No. 031]
- 11) Green, R. 1972. Alberta Geological Survey. Geological Map of Alberta. [AGS MAP 027]
- 12) Hamilton, W. H., W. Langenberg, M. C. Price, and D. K. Chao. 1998. Alberta Geological Survey. Geological Map of Alberta (hardcopy). [AGS MAP 236]
- 13) Hydrogeological Consultants Ltd. Jul-1973. Department of Lands and Forests, Park Planning Branch. Preliminary Resources Inventory: Geology & Hydrogeology. Crimson Lake Provincial Park. 040-08 W5M. — (unpublished contract report - Jul-1973.) [73-127.00] [83B06 .C74L3P7 1973/07]
- 14) Hydrogeological Consultants Ltd. Dec-1974. Gulf Oil Canada Ltd. Water Level Recovery: Water Source Well Near Drayton Valley: Autumn 1974. Drayton Valley Area. 048-06, 048-09, 047-07 W5M. — (unpublished contract report - Dec-1974.) [<->] [83G02 .D7V3 1974/12]
- 15) Hydrogeological Consultants Ltd. Aug-1977. Alberta Transportation. Airport Terminal Building: Water Well. Rocky Mountain House Area. 11-040-07 W5M. — (unpublished contract report - Aug-1977.) [<->] [83B07 .R6264M6H6 1977/08]

- 16) Hydrogeological Consultants Ltd. Jan-1980. Suncor Inc. Unit 3: 1979 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Jan-1980.) [<->] [83B08 .M4R5 1980/01]
- 17) Hydrogeological Consultants Ltd. Mar-1981. Suncor Inc. 1980 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Mar-1981.) [<->] [83B08 .M4R5 1981/03]
- 18) Hydrogeological Consultants Ltd. Apr-1981. Texas Pacific Oil Canada Ltd. J. Songer, J. Cliff Morgan and D. Ladd: Water Wells Investigation: November 1980 to January 1981. Rocky Mountain House Area. 16-040-08 W5M. — (unpublished contract report - Apr-1981.) [80-115.00] [83B07 .R6264M6H6 1981/04]
- 19) Hydrogeological Consultants Ltd. Jan-1982. Suncor Inc. Unit 3: 1981 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Jan-1982.) [81-009.00] [83B08 .M4R5 1982/01]
- 20) Hydrogeological Consultants Ltd. Jan-1983. Suncor Inc. 1982 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Jan-1983.) [82-009.00] [83B08 .M4R5 1983/01]
- 21) Hydrogeological Consultants Ltd. Mar-1983. Dekalb Petroleum Corporation. P. Szoke Aquifer Testing. Rocky Mountain House Area. 30-040-06 W5M. — (unpublished contract report - Mar-1983.) [83-119.01] [83B07 .R6264M6H6 1983/11a]
- 22) Hydrogeological Consultants Ltd. Sep-1983. Dekalb, Szoke Aquifer Test, NW 30-40-06 W5M. 30-040-06 W5M. — (unpublished contract report - Sep-1983.) [<->]
- 23) Hydrogeological Consultants Ltd. Nov-1983a. Dekalb Petroleum Corporation. F. Dobia Aquifer Testing. Stauffer Area. 19-037-04 W5M. — (unpublished contract report - Nov-1983.) [83-125.00] [83B02 .S728 1983/11]
- 24) Hydrogeological Consultants Ltd. Nov-1983b. Dekalb Petroleum Corporation. G. Lea Aquifer Testing. Rocky Mountain House Area. 25-040-07 W5M. — (unpublished contract report - Nov-1983.) [83-119.00] [83B07 .R6264M6H6 1983/11]
- 25) Hydrogeological Consultants Ltd. Nov-1983c. Dekalb Petroleum Corporation. H. Herber Aquifer Testing. Stauffer Area. 05-037-04 W5M. — (unpublished contract report - Nov-1983.) [83-120.00] [83B02 .S728 1983/11a]
- 26) Hydrogeological Consultants Ltd. Jan-1984. Suncor Inc. 1983 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Jan-1984.) [83-009.00] [83B08 .M4R5 1984/01]
- 27) Hydrogeological Consultants Ltd. May-1984. Dekalb Petroleum Corporation. O. Coleman Aquifer Testing. Stauffer Area. 06-037-04 W5M. — (unpublished contract report - May-1984.) [84-110.00] [83B02 .S728 1984/05]
- 28) Hydrogeological Consultants Ltd. Jun-1984. Dekalb Petroleum Corporation. Oliver Aquifer Testing. Caroline Area. 25-035-07 W5M. — (unpublished contract report - Jun-1984.) [83-155.00] [83B02 .C3765 1984/06]

- 29) Hydrogeological Consultants Ltd. Aug-1984. Dekalb Petroleum Corporation. Greenwood Aquifer Testing. Lesleyville Area. 06-040-05 W5M. — (unpublished contract report - Aug-1984.) [84-135.00] [83B07 .L3475 1984/08]
- 30) Hydrogeological Consultants Ltd. Sep-1984. Dekalb Petroleum Corporation. Farnell-Misner Aquifer Testing. Rocky Mountain House Area. 32-039-05 W5M. — (unpublished contract report - Sep-1984.) [84-141.00] [83B07 .R6264M6H6 1984/09]
- 31) Hydrogeological Consultants Ltd. Jan-1985a. Dekalb Petroleum Corporation. J. Martin Aquifer Testing. Alhambra Area. 07-040-05 W5M. — (unpublished contract report - Jan-1985.) [84-147.00] [83B07 .A43 1985/01]
- 32) Hydrogeological Consultants Ltd. Jan-1985b. Suncor Inc. 1984 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Jan-1985.) [84-009.00] [83B08 .M4R5 1985/01]
- 33) Hydrogeological Consultants Ltd. Jun-1985. Alberta Environment, Earth Sciences Division, Hydrogeology Branch. Emergency Groundwater Testing Program: Draft. Part of Alberta. — (unpublished contract report - Jun-1985.) [85-159.00] [AB .A42 1985/06]
- 34) Hydrogeological Consultants Ltd. Aug-1985. Esso Resources Canada Limited. Wadams Domestic Water Well. Rocky Mountain House Area: Ferrier Area. 20-038-07 W5M. — (unpublished contract report - Aug-1985.) [85-143.00] [83B07 .R6264M6H6 1985/08]
- 35) Hydrogeological Consultants Ltd. Oct-1985a. Dekalb Petroleum Corporation. R. Brown Aquifer Testing. Rimbey Area. 01-041-05 W5M. — (unpublished contract report - Oct-1985.) [85-128.00] [83B10 .R55 1985/10]
- 36) Hydrogeological Consultants Ltd. Oct-1985b. Esso Resources Canada Limited. Quinlan Domestic Water Well Testing. Rocky Mountain House Area. 20-037-07 W5M. — (unpublished contract report - Oct-1985.) [85-133.00] [83B07 .R6264M6H6 1985/10]
- 37) Hydrogeological Consultants Ltd. Jan-1986. Suncor Inc. 1985 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Jan-1986.) [85-009.00] [83B08 .M4R5 1986/01]
- 38) Hydrogeological Consultants Ltd. Feb-1986. Dekalb Petroleum Corporation. D. Neufeld Domestic Water Well. Eckville Area. 05-041-04 W5M. — (unpublished contract report - Feb-1986.) [85-129.00] [83B10 .E25 1986/02]
- 39) Hydrogeological Consultants Ltd. Jun-1986. Esso Resources Canada Limited. Langford Aquifer Testing. Rocky Mountain House Area: Ferrier Area. 20-038-07 W5M. — (unpublished contract report - Jun-1986.) [85-144.00] [83B07 .R6264M6H6 1986/06]
- 40) Hydrogeological Consultants Ltd. Sep-1986. Dekalb Petroleum Corporation. Dekalb et al Sundre: Sevens Aquifer Testing. Sundre Area. 12-034-05 W5M. — (unpublished contract report - Sep-1986.) [85-164.00] [82O15 .S9 1986/09]
- 41) Hydrogeological Consultants Ltd. Oct-1986. Esso Resources Canada Limited. Bigelow Aquifer Testing. Rocky Mountain House Area. 28-038-07 W5M. — (unpublished contract report - Oct-1986.) [86-145.00] [83B07 .R6264M6H6 1986/10]

- 42) Hydrogeological Consultants Ltd. Nov-1986. Esso Resources Canada Limited. Nissen-Chemysen Aquifer Testing. Rocky Mountain House Area. 11-038-07 W5M. — (unpublished contract report - Nov-1986.) [86-176.00] [83B07 .R6264M6H6 1986/11]
- 43) Hydrogeological Consultants Ltd. Dec-1986. Dekalb Petroleum Corporation. Dekalb et al Willgr: Reid Aquifer Testing. Rocky Mountain House Area. 29-039-05 W5M. — (unpublished contract report - Dec-1986.) [86-111.00] [83B07 .R6264M6H6 1986/12]
- 44) Hydrogeological Consultants Ltd. Mar-1987a. Amerada Minerals Corporation of Canada Ltd. Water Source Study. Ferrier Belly River: Unit No. 1. 041-08 W5M. — (unpublished contract report - Mar-1987.) [<->] [83B11 .R6264M6H6 1987/03]
- 45) Hydrogeological Consultants Ltd. Mar-1987b Suncor Inc. 1986 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Mar-1987.) [86-009.00] [83B08 .M4R5 1987/03]
- 46) Hydrogeological Consultants Ltd. Feb-1988. Suncor Inc. 1987 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Feb-1988.) [87-009.00] [83B08 .M4R5 1988/02]
- 47) Hydrogeological Consultants Ltd. Jun-1988. Rocky Wood Preservers Ltd. 1988 Hydrogeology Report. Rocky Mountain House Area. 18-039-07 W5M. — (unpublished contract report - Jun-1988.) [88-152.00] [83B07 .R6264M6H6 1988/06]
- 48) Hydrogeological Consultants Ltd. Sep-1989. Amerada Minerals Corporation of Canada Ltd. 1989 Groundwater Exploration Project. Rocky Mountain House Area. 08-041-08 W5M. — (unpublished contract report - Sep-1989.) [<->] [83B11 .R6264M6H6 1989/09]
- 49) Hydrogeological Consultants Ltd. Nov-1989a. Dekalb Energy Canada Ltd. Dekalb-Med: R. Bruinsma Aquifer Testing. Condor Area. 24-038-05 W5M. — (unpublished contract report - Nov-1989.) [89-107.00] [83B07 .C66 1989/11]
- 50) Hydrogeological Consultants Ltd. Nov-1989b. Dekalb Energy Canada Ltd. Dekalb-Sylake: Vohs Aquifer Testing. Raven Area. 29-036-04 W5M. — (unpublished contract report - Nov-1989.) [87-130.00] [83B02 .R385 1989/11]
- 51) Hydrogeological Consultants Ltd. Jan-1991. Amerada Minerals Corporation of Canada Ltd. 1990 Annual Groundwater Monitoring Report. Ferrier Belly River: Unit No. 1. 041-08 W5M. — (unpublished contract report - Jan-1991.) [90-051.00] [83B11 .R6264M6H6 1991/01]
- 52) Hydrogeological Consultants Ltd. Mar-1991a. Dekalb Energy Canada Ltd. Dekalb et al WillGr.: J. Wickens Aquifer Testing. Rocky Mountain House Area. 15-041-06 W5M. — (unpublished contract report - Mar-1991.) [89-149.01] [83B10 .R6264M6H6 1991/03]
- 53) Hydrogeological Consultants Ltd. Mar-1991b. Dekalb. Wickens Aquifer Test. NE 15-41-06 W5M. 15-041-06 W5M. — (unpublished contract report - Mar-1991.) [89-149.00]
- 54) Hydrogeological Consultants Ltd. Aug-1991. Suncor Inc. 1988-1990 Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Aug-1991.) [90-009.00] [83B08 .M4R5 1991/08]

- 55) Hydrogeological Consultants Ltd. Sep-1992. Suncor Inc. 1991 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Sep-1992.) [91-009.00] [83B08 .M4R5 1992/09]
- 56) Hydrogeological Consultants Ltd. Oct-1993. NEWALTA Corporation. Stauffer Reclamation Plant: Shallow Groundwater Evaluation. Stauffer Area. 11-037-05 W5M. — (unpublished contract report - Oct-1993.) [93-156.00] [83B02 .S728 1993/10]
- 57) Hydrogeological Consultants Ltd. Nov-1993. NEWALTA Corporation. Stauffer Reclamation Plant: 1993 Groundwater Program. Stauffer Area. 11-037-05 W5M. — (unpublished contract report - Nov-1993.) [93-171.00] [83B02 .S728 1993/11]
- 58) Hydrogeological Consultants Ltd. Jan-1994. Amoco Canada Petroleum Company Ltd. Cardium Unit No. 7: 1992-1993 Groundwater Monitoring Report. Pembina Area. 047-09 W5M. — (unpublished contract report - Jan-1994.) [93-055.00] [83G03 .P45 1994/01]
- 59) Hydrogeological Consultants Ltd. Mar-1994. Amerada Hess Canada Ltd. Ferrier Belly River Unit No. 1: 1992-1993 Groundwater Monitoring Report. Rocky Mountain House Area. 08-041-08 W5M. — (unpublished contract report - Mar-1994.) [93-051.00] [83B11 .R6264M6H6 1994/03]
- 60) Hydrogeological Consultants Ltd. May-1994. Suncor Inc. 1992-1993 Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - May-1994.) [93-009.00] [83B08 .M4R5 1994/05]
- 61) Hydrogeological Consultants Ltd. Oct-1994. NEWALTA Corporation. Stauffer Reclamation Plant: July 1994 Groundwater Monitoring Report. Stauffer Area. 11-037-05 W5M. — (unpublished contract report - Oct-1994.) [94-148.00] [83B02 .S728 1994/10]
- 62) Hydrogeological Consultants Ltd. Mar-1995a. Amerada Hess Canada Ltd. Ferrier Belly River Unit No. 1: 1994 Groundwater Monitoring Report. Rocky Mountain House Area. 041-08 W5M. — (unpublished contract report - Mar-1995.) [94-051.00] [83B11 .R6264M6H6 1995/03]
- 63) Hydrogeological Consultants Ltd. Mar-1995b. Amoco Canada Petroleum Company Ltd. Pembina Cardium Unit No. 7: 1994 Groundwater Monitoring Report. Lodgepole Area. 047-09 W5M. — (unpublished contract report - Mar-1995.) [94-055.00] [83G03 .L6 1995/03a]
- 64) Hydrogeological Consultants Ltd. Apr-1995. Suncor Inc. Resources Group. 1994 Annual Groundwater Monitoring Report. Medicine River Area. 038-04 W5M. — (unpublished contract report - Apr-1995.) [94-009.00] [83B08 .M4R5 1995/04]
- 65) Hydrogeological Consultants Ltd. May-1996. Amerada Hess Canada Ltd. Ferrier Belly River Unit No. 1: 1995 Groundwater Monitoring Report. Rocky Mountain House Area. 041-08 W5M. — (unpublished contract report - May-1996.) [MR-051.01] [83B11 .R6264M6H6 1996/05]
- 66) Hydrogeological Consultants Ltd. Jul-1996. Amerada Hess Canada Ltd. Increased Diversion from the North Saskatchewan River. Rocky Mountain House Area. 18-040-07 W5M. — (unpublished contract report - Jul-1996.) [96-122.00] [83B07 .R6264M6H6 1996/07]
- 67) Hydrogeological Consultants Ltd. Aug-1996a. Amoco Canada Petroleum Company Ltd. Cardium Unit No. 7: 1995 Annual Groundwater Monitoring Report. Pembina Area. 047-09 W5M. — (unpublished contract report - Aug-1996.) [MR-055.01] [83G03 .P45 1996/08]