



Module 6.1.4.3 SPECIFIC ACTION PLAN PLUMBING WORK

HEALTH AND SAFETY ACTION PLAN FOR REPAIR AND CONSTRUCTION PROJECTS AT THE JOHN H.
CHAPMAN SPACE CENTRE

1. Worker's skills

Every worker assigned to this work must satisfy the requirements of the plumbing code.

2. Cuts on the hands

The worker must wear gloves in addition to the personal protective equipment listed in the general action plan.

3. Work method

Before pressurizing a pipe, make sure the plugs are fully inflated and in position. Clear the work area to avoid injuries in the event a plug or the contents are expelled from the pipe.

In the event of pressure loss due to a plug, stay back until the pressure has fully dissipated, then replace the plug.

Do not pressurize pipes above the values stipulated in the drawings and specifications.