



# Important Safety Notice


January 14, 2002

To: Our Valued Customer

Re: Voluntary Refit  
Model MD3021 AirForce Inflatable Pouch PFD

The MD3021 inflatable pouch is in compliance with UL1180 requirements, the Canadian Addendum, and the Canadian Coast Guard approval, however we have determined that the potential exists for a possible separation of the inflatable cell from its belted pouch carrier during inflation.

Mustang Survival is requesting all MD3021 inflatable pouches be returned to our factory for refit. Check the diagrams below to see if your unit needs to be refit. You will be responsible for shipping your product back to us. It will be returned to you, as quickly as possible, pre-paid. You will need to obtain a return authorization number from our Customer Service Department and we request that you ship your unit without the CO2 cylinder. Please send your unit back to Mustang Survival, Unit #104, 3820 Jacombs Road, Richmond BC V6V 1Y6. For a return authorization number or for further information please feel free to call our Customer Service Department at 1.800.661.6181 or email us at [mustang@mustangsurvival.com](mailto:mustang@mustangsurvival.com).



Thank you very much for your cooperation with this important matter.

Yours Sincerely

Bob Askew  
Chief Operating Officer  
Mustang Survival Corp.

For more information, contact:  
Mustang Survival  
3810 Jacombs Road, Richmond, BC V6V 1Y6



Phone: (604) 270-8631 Fax: (604) 273-6466  
e-mail: [mustang@mustangsurvival.com](mailto:mustang@mustangsurvival.com)  
website: [www.mustangsurvival.com](http://www.mustangsurvival.com)