WATER WELLS RECOMMENDED FOR FIELD VERIFICATION (continued)

| | | Aquifer | Date Water | Completed Depth | | NPWL | | |
|-------------------------------|------------------|----------------|--------------|-----------------|-------|--------|-------|---------------|
| Owner | Location | Name | Well Drilled | Metres | Feet | Metres | Feet | UID |
| Strandberg, Bert | SW 02-024-03 W5M | Dalehurst | 02-Oct-98 | 42.67 | 140.0 | 8.32 | 27.3 | M36727.992173 |
| Stussi, Hans | SW 27-026-04 W5M | Dalehurst | 05-Sep-79 | 22.86 | 75.0 | 18.9 | 62.0 | M35379.088609 |
| Style Properties Ltd. | SW 12-024-28 W4M | Lacombe | 22-Mar-77 | 67.05 | 220.0 | 16 | 52.5 | M35377.188245 |
| Style Properties Ltd. | SE 12-024-28 W4M | Lacombe | 30-Mar-77 | 60.96 | 200.0 | 15.85 | 52.0 | M35377.205673 |
| Sunderland, Wes | SE 11-025-28 W4M | Lacombe | 27-Oct-86 | 28.65 | 94.0 | 13.72 | 45.0 | M35377.205647 |
| Sutherland, Glen | NW 04-024-28 W4M | Lacombe | 01-May-72 | 86.25 | 283.0 | 35.05 | 115.0 | M35377.205666 |
| Swalander, J. | SE 17-028-05 W5M | Disturbed Belt | 01-Aug-75 | 54.86 | 180.0 | 12.19 | 40.0 | M35379.088408 |
| Szabon, B. | 15-11-025-27 W4M | Lacombe | 29-Sep-81 | 30.48 | 100.0 | 3.9 | 12.8 | M35377.193297 |
| Tait, Bob | NW 19-025-02 W5M | Dalehurst | 07-Oct-74 | 51.20 | 168.0 | 41.15 | 135.0 | M35379.108068 |
| Tanner, R. | NW 31-023-27 W4M | Lacombe | 07-Oct-76 | 39.62 | 130.0 | 14.63 | 48.0 | M35377.187501 |
| Taschke, Herbert | 01-10-028-05 W5M | Disturbed Belt | 06-Jul-71 | 42.67 | 140.0 | 35.05 | 115.0 | M35379.088256 |
| Thomas, Gordon | SW 03-023-27 W4M | Lacombe | 23-Oct-75 | 12.80 | 42.0 | 8.53 | 28.0 | M35377.187158 |
| Thomas, Gordon | SW 03-023-27 W4M | Lacombe | 01-Apr-70 | 17.07 | 56.0 | 9.75 | 32.0 | M35377.187159 |
| Thompson, Mike | SW 28-028-04 W5M | Dalehurst | 04-Oct-79 | 26.82 | 88.0 | 16.76 | 55.0 | M35379.088472 |
| Thorogood, Cliff | NE 02-024-04 W5M | Disturbed Belt | 24-May-74 | 23.47 | 77.0 | 0.61 | 2.0 | M35379.088882 |
| Tremblay, Alexander | SE 34-027-02 W5M | Dalehurst | 12-Sep-75 | 54.86 | 180.0 | 32 | 105.0 | M35379.092241 |
| Trosch, Ernie | 01-10-028-05 W5M | Disturbed Belt | 05-Nov-78 | 60.96 | 200.0 | 36.57 | 120.0 | M35379.088259 |
| Valgardson, Ray | SW 08-027-28 W4M | Dalehurst | 20-Sep-73 | 24.38 | 80.0 | 10.67 | 35.0 | M35377.207737 |
| Vanderburgh, Leo | NE 33-025-28 W4M | Lacombe | 16-Aug-74 | 28.95 | 95.0 | 9.14 | 30.0 | M35377.205597 |
| Verrall, Peter | SE 02-026-03 W5M | Dalehurst | 17-Feb-72 | 77.72 | 255.0 | 60.96 | 200.0 | M35379.115156 |
| Wade, Jack | 08-06-028-26 W4M | Lacombe | 09-Jun-80 | 46.33 | 152.0 | 19.81 | 65.0 | M35377.165203 |
| Wagner, Ervin F. | 06-10-027-26 W4M | Haynes | 20-Jun-79 | 41.15 | 135.0 | 12.19 | 40.0 | M35377.202244 |
| Watson, J. A. | SW 32-024-28 W4M | Lacombe | 16-Apr-79 | 46.63 | 153.0 | 14.02 | 46.0 | M35377.188615 |
| Wearmouth, Walter | SW 02-026-03 W5M | Dalehurst | 01-Mar-81 | 45.72 | 150.0 | 39.62 | 130.0 | M35379.115160 |
| Weber, Sally | SE 10-027-02 W5M | Dalehurst | 16-Sep-74 | 17.68 | 58.0 | 12.5 | 41.0 | M35379.092049 |
| Wegener, Ralph | SW 10-028-26 W4M | Lacombe | 08-Jun-82 | 50.29 | 165.0 | 16.76 | 55.0 | M35377.165213 |
| Wesco Property DevelopmentLtd | | Dalehurst | 21-Jun-76 | 26.52 | 87.0 | 14.32 | 47.0 | M35379.090479 |
| Westenson, Ted | NE 23-026-04 W5M | Dalehurst | 01-Jul-74 | 28.95 | 95.0 | 14.93 | 49.0 | M35379.090211 |
| Wheatley, F. R. | SW 03-024-27 W4M | Lacombe | 28-Sep-79 | 40.54 | 133.0 | 2.44 | 8.0 | M35377.187677 |
| Wheeler, Arnold | SW 25-024-03 W5M | Dalehurst | 14-May-80 | 32.92 | 108.0 | 18.29 | 60.0 | M35379.090396 |
| Wheeler, L. | NW 25-021-27 W4M | Lacombe | 22-Jun-77 | 51.81 | 170.0 | 37.79 | 124.0 | M35377.180360 |
| Wiebe, Peter | SW 18-023-28 W4M | Lacombe | 27-Jul-85 | 35.05 | 115.0 | 12.19 | 40.0 | M35377.183815 |
| Wiens, Henry | NE 18-028-05 W5M | Disturbed Belt | 02-Jul-76 | 28.95 | 95.0 | 12.19 | 40.0 | M35379.088558 |
| Williams, Dan | SE 34-026-01 W5M | Dalehurst | 03-May-74 | 15.24 | 50.0 | 12.19 | 40.0 | M35379.091132 |
| Willie, R. | NE 13-028-05 W5M | Dalehurst | 15-Aug-75 | 25.30 | 83.0 | 11.58 | 38.0 | M35379.088642 |
| Wilson, Dave | 12-22-024-03 W5M | Dalehurst | 18-Apr-75 | 22.86 | 75.0 | 6.1 | 20.0 | M35379.090261 |
| Winkler, Everest E. | NW 34-021-27 W4M | Haynes | 01-May-74 | 73.15 | 240.0 | 57.91 | 190.0 | M35377.180371 |
| Wise, Wayne | SW 13-024-28 W4M | Lacombe | 30-May-77 | 19.81 | 65.0 | 6.1 | 20.0 | M35377.188274 |
| Wray, Doug | 05-26-027-27 W4M | Lacombe | 27-Mar-81 | 45.11 | 148.0 | 15.85 | 52.0 | M35377.202866 |
| Zillman, Jim | SW 35-027-02 W5M | Dalehurst | 10-May-76 | 18.29 | 60.0 | 7.62 | 25.0 | M35379.078027 |

M.D. of ROCKY VIEW-OPERATED WATER WELLS

| | | Aquifer | Date Water | Completed Depth | | NPWL | | |
|------------------------|------------------|-----------|--------------|-----------------|-------|--------|------|---------------|
| Owner | Location | Name | Well Drilled | Metres | Feet | Metres | Feet | UID |
| M.D. of Rockyford #44 | SW 13-026-27 W4M | 31-Jul-74 | Lacombe | 13.72 | 45.0 | 4.57 | 15.0 | M35377.223299 |
| M.D. Rocky View No. 44 | SW 12-025-03 W5M | 26-Aug-86 | Dalehurst | 41.15 | 135.0 | 3.66 | 12.0 | M35379.090592 |

